STATE OF CALIFORNIA • DEPARTMENT OF TRANSPORTATION **STRUCTURES REPRESENTATIVE'S REPORT** HC-0010 (CUSTOMIZED)

JOB STAMP

04-0120M4 (04-00000022) 04-SF-80-1.6/2.7 San Francisco Oakland Bay Bridge Oakland Touchdown - Phase 2

REPORT NO.	121	to			DATE October 03, 2012	M T W Th F S S
SHIFT HOUR	START	06:45	STOP	16:00	TEMPERATURE	
WEATHER	Clear					

- 1. Ade confirmed that FWI needs to provide a letter absolving the Design Joint Venture of any liabilities from their hiring of Cadre to produce geometry for the interior stem panel forms. Received a letter to that effect from FWI in the afternoon. Forwarded onto Ade and the Design JV.
- 2. Complete OBG cross sections for use in field stem layouts.
- 3. Coordination Meeting no issues reconfirmed closures of the access trestle next week at night.
- 4. Weekly OTD II Meeting
 - a. Stair tower is being erected for F/W access with K-Rail being provided for protection from traffic.
 - b. SWPPP Water truck leaking water needs to be addressed.
 - c. 72 hour closure coordinate with Gabe on the matrix.
 - d. Soffit check with Tyler Darland on the Doyle Drive projects for similar application.
 - e. F/W over water had one of its piles mislocated. Will need calcs and a detail from FWI to close out the issue.
 - f. CMC need to have a pre-splice meeting.
 - g. UIS need to have a pre-weld meeting.
- 5. RFI 55 checked with AECOM and a response if forthcoming.
- 6. Sent out email to Sajid to check on Wall A loads for unbalanced loading due to soil removal from the OTDII side of the wall.
- 7. Clarified to FWI that the pedestal reinforcement need not intersect the column bars which are short. Use other bars to support he hoops.
- 8. Issued deck drain submittal response.
- 9. Thanh escorting Channel 7 Newswoman through the job site.
- 10. Received a revised shop drawing from Cadre for the service platform anchor bolts.